

EXHIBIT 3

EXHIBIT 8

IC SPECIALTY SERVICES ARTIFACT/EVIDENCE LOG 1			
INSURED:	Nuttall	CLM # :	5015617702
Evidence Custodian:	Cristal VanDongen	FILE #:	22-39937
Item Number	Description	Date Collected:	
1	fire damaged hover board	4-Feb-22	
2			
3			
4			
5			
6			

IC SPECIALTY SERVICES ARTIFACT/EVIDENCE LOG 2			
INSURED:	Nuttall	CLM # :	5015617702
Evidence Custodian:	Alex Hoff	FILE #:	22-39937
Item Number	Description	Date Collected:	
1	Smoke detector	8/2 to 8/4, 2022	
2	Smoke detector	8/2 to 8/4, 2022	
3	Smoke detector	8/2 to 8/4, 2022	
4	Smoke detector	8/2 to 8/4, 2022	
5	Smoke detector	8/2 to 8/4, 2022	
6	Smoke detector	8/2 to 8/4, 2022	
7	Smoke detector	8/2 to 8/4, 2022	
8	Smoke detector	8/2 to 8/4, 2022	
9	Smoke detector	8/2 to 8/4, 2022	
10	mattress - northeast bedroom	8/2 to 8/4, 2022	
11	mattress - northeast bedroom	8/2 to 8/4, 2022	
12	remnants of smoke detector - SW bedroom	8/2 to 8/4, 2022	
13	battery from SW bath/bedroom 8.75 V	8/2 to 8/4, 2022	
14	debris from behind refridgertor	8/2 to 8/4, 2022	
15	battery SW bedroom 8.47 V	8/2 to 8/4, 2022	
16	motor from the threshold for bedroom #4	8/2 to 8/4, 2022	
17	smoke alarm base - garage, west wall	8/2 to 8/4, 2022	
18	smoke detector base - basement	8/2 to 8/4, 2022	
19	Weather Head	8/2 to 8/4, 2022	
20	Electrical circuit and breaker - bedroom #4	8/2 to 8/4, 2022	
21	Electrical circuits - bedroom #4	8/2 to 8/4, 2022	
22	electrical receptacle - garage	8/2 to 8/4, 2022	
23	face plates - bedroom #4	8/2 to 8/4, 2022	
24	circuit breaker - east exterior electrical receptacle	8/2 to 8/4, 2022	
25	charging cords - kitchen	8/2 to 8/4, 2022	
26	debris from floor of closet - bedroom #4	8/2 to 8/4, 2022	
27	floor debris - bedroom #4	8/2 to 8/4, 2022	
28	solid debris - exterior, east side of the structure	8/2 to 8/4, 2022	
29	solid debris - exterior, east side of the structure	8/2 to 8/4, 2022	
30	refridgerator	8/2 to 8/4, 2022	
A1a.	Debris	8/2 to 8/4, 2022	

A1b.	smoke detector components	8/2 to 8/4, 2022
A1c.	carpet and miscellaneous debris	8/2 to 8/4, 2022
A2a.	debris	8/2 to 8/4, 2022
A2b.	miscellaneous	8/2 to 8/4, 2022
A3a.	debris	8/2 to 8/4, 2022
A3b.	miscellaneous	8/2 to 8/4, 2022
B1a.	debris	8/2 to 8/4, 2022
B1b.	2 battery cells (hover board)	8/2 to 8/4, 2022
B1c.	miscellaneous debris	8/2 to 8/4, 2022
B2a.	debris	8/2 to 8/4, 2022
B2b.	debris	8/2 to 8/4, 2022
B3a.	debris	8/2 to 8/4, 2022
B3b.	debris	8/2 to 8/4, 2022
B3c.	debris	8/2 to 8/4, 2022
B3d.	debris	8/2 to 8/4, 2022
B3e.	miscellaneous	8/2 to 8/4, 2022
C1a.	debris	8/2 to 8/4, 2022
C1b.	miscellaneous	8/2 to 8/4, 2022
C2a.	debris	8/2 to 8/4, 2022
C2b.	miscellaneous	8/2 to 8/4, 2022
C3a.	debris	8/2 to 8/4, 2022
C3b.	debris	8/2 to 8/4, 2022
C3c.	miscellaneous	8/2 to 8/4, 2022
D1a.	debris	8/2 to 8/4, 2022
D1b.	miscellaneous	8/2 to 8/4, 2022
D2a.	electrical wiring	8/2 to 8/4, 2022
D2b.	portable heater and associated electrical	8/2 to 8/4, 2022
D2c.	extension cord	8/2 to 8/4, 2022
D2d.	ashtray	8/2 to 8/4, 2022
D2e.	misc. debris and electrical components	8/2 to 8/4, 2022
D2f.	light component	8/2 to 8/4, 2022
D2g.	aluminum wiring from beneath the weather head	8/2 to 8/4, 2022
D2h.	extension cord and electrical receptacle	8/2 to 8/4, 2022
D2i.	miscellaneous debris	8/2 to 8/4, 2022
D2j.	miscellaneous debris	8/2 to 8/4, 2022
D2k.	miscellaneous debris	8/2 to 8/4, 2022
D2l.	debris from above the solid mas	8/2 to 8/4, 2022
D2m.	debris	8/2 to 8/4, 2022
D2n.	debris	8/2 to 8/4, 2022